

## FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

- 1 Name of Officer : Bindhu.B.A
- 2 Name of School : MAR GREGORIOS E.M SCHOOL , NORTH PARAVOOR
- 3 Location with name of Education District, Sub-District : Aluva Education District , N. paravoor Sub District .
- 4 Classification of buildings as specified in column 4 of application for Fitness Certificate and Size : Details over leaf
- 5 Period for which the certificate is issued : For the acadamic Year 2025-26
- 6 Nature of defect if any :
- a) Foundation and basement : Satisfactory
- b) Superstructure : Satisfactory
- c) Doors & windows : Satisfactory
- d) Wood work wrought & put up : Satisfactory
- e) Roof : Satisfactory
- f) Flooring : Satisfactory
- g) Miscellaneous (Cracks etc.) : Satisfactory
- 7 Any major defects noticed which will render the building unsafe in any manner : Nil
- 8 Whether the maintenance works have been done properly : Yes
- 9 Whether the structure is sound or not for conducting classes : The structure is sound to conduct the classes under normal weather condition.

### Notes:

- 1 The stability of the structure should be examined also with reference to location, altitude, intensity, of wind, exposure to flood etc.
- 2 Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 19.01.2026 and found to be fit/unfit to conduct classes for the period 19.01.2026 to 31.03.2026 under normal weather condition for the reasons stated above.

Place : N.Paravur  
Date : 19.01.2026



Signature :  
Designation :

ASST. ENGINEER  
L.S.G.D  
MUNICIPAL OFFICE  
NORTH PARAVUR

FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

Classification of buildings as specified in column 4 of application for fitness certificate and size.

Name of school

MAR GREGORIOS E.M SCHOOL, NORTH PARAVOOR

DETAILS OF BUILDING

TWO STORIED BUILDING (NORTH SIDE)

CLASS ROOM	1*5*5.10*3.55 (G.F)
HALL	1*16.20*5.10*3.55 (G.F)
STORE	1*3.20*3.05*3.55 (G.F)
CLASS ROOM	1*3.30*5.10*3.55 (G.F)
VERANDHA	1*28*1.60*3.55 (G.F)
TEACHERS ROOM	1*3.05*2.20*3.55 (F.F)
READING ROOM	1*2*2.35*3.55 (F.F)
REST ROOM	1*2*2.35*3.55 (F.F)
HALL	1*24.95*5.10*3.55 (F.F)
VERANDHA	1*26*1.80*3.55

TWO STORIED BUILDING

CLASS ROOM	3*6.20*3.65 (G.F)
VERANDHA	1*22.40*1.50*3.05 (G.F)
CLASS ROOM	3*6.20*6.10*3.65 (F.F)
VERANDHA	1*22.40*1.50*3.05 (F.F)
TEACHERS ROOM	1*3.05*2.20*3.55 (F.F)
READING ROOM	1*2*2.35*3.55 (F.F)
REST ROOM	1*2*2.35*3.55 (F.F)
HALL	1*24.95*5.10*3.55 (F.F)
VERANDHA	1*26*1.80*3.55

TRIPPLE STORIED BUILDING( south side)

CLASS ROOM	4*6.10*6.10*3.75 (G.F)
VERANDHA	1*38.08*1.80*3.75 (G.F)
STAGE	1*8*8.20*3.75 (G.F)
CLASS ROOM	4*6.10*6.10*3.75 (F.F)
CLASS ROOM	4*6.10*8.20*3.75 (F.F)
VERANDHA	1*32.08*1.80*3.75 (G.F)
CLASS ROOM	4*6.10*6.10*3.75 (F.F)
CLASS ROOM	4*8*8.20*3.75 (F.F)
VERANDHA	1*32.08*1.80*3.75 (F.F)
TOILET	9 NOS
URINAL	9 NOS



*L.S.G.D.*  
 ASSY. ENGINEER  
 L.S.G.D  
 MUNICIPAL OFFICE  
 NORTH PARAVUP