

FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

1	Name of Officer	:	BINDU B A
2	Name of School	:	MAR GREGORIOS E.M SCHOOL , NORTH PARAVOOR
3	Location with name of Education District, Sub-District	:	Aluva Education District , N. paravoor Sub District .
4	Classification of buildings as specified in column 4 of application for Fitness Certificate and Size	:	Details over leaf
5	Period for which the certificate is issued	:	For the acadamic Year 2026-2027
6	Nature of defect if any	:	
	a) Foundation and basement	:	Nil
	b) Superstructure	:	Nil
	c) Doors & windows	:	Nil
	d) Wood work wrought & put up	:	Nil
	e) Roof	:	Nil
	f) Flooring	:	Nil
	g) Miscellaneous (Cracks etc.)	:	Nil
7	Any major defects noticed which will render the building unsafe in any manner	:	Nil
8	Whether the maintenance works have been done properly	:	Yes
9	Whether the structure is sound or not for conducting classes	:	The structure is sound to conduct the classes under normal weather

Notes:

- 1 The stability of the structure should be examined also with reference to location, altitude, intensity, of wind, exposure to flood etc.
- 2 Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 23.05.2026 and found to be fit/unfit to conduct classes for the period 01.06.2026 to 31.03.2027 under normal weather condition for the reasons stated above.

Place : N.Paravur
Date : 23-05-26



Signature : 
Designation :
ASST. ENGINEER
L.S.G.D
MUNICIPAL OFFICE
NORTH PARAVUR

ALL THE UA BUILDINGS ARE REGULARISED BE FORE NEXT The Acadamic Year 2026-2027

Classification of buildings as specified in column 4 of application for fitness certificate and size.

Name of school

MAR GREGORIOS E.M SCHOOL, NORTH
PARAVOOR

DETAILS OF BUILDING

TWO STORIED BUILDING (NORTH SIDE)

RCC BUILDING BLOCK 1

CLASS ROOM GF	1*6.00*6.00*3.55
STAFF ROOM GF	2*6.00*6.00*3.55
STAFF ROOM GF	1*9.00*6.00*3.55
OFFICE ROOM GF	1*9.00*2.00*3.60
CLASS ROOM FF	3*6.00*6.00*3.55
COMPUTER ROOM FF	1*6.00*6.00*3.55
CLASS ROOM SF	4*6.00*6.00*3.60

RCC BUILDING BLOCK 2


CLASS ROOM GF	3*6.10*6.10*3.60
VERANDHA GF	1*22.40*1.80*3.60
CLASS ROOM FF	3*6.10*6.10*3.60
VERANDHA FF	1*22.40*1.80*3.60

RCC BUILDING BLOCK 3

STAGE	1*10.00*8.60*3.60
CLASS ROOM GF	4*6.10*6.10*3.70
VERANDHA GF	1*31.00*1.80*3.70
CLASS ROOM FF	4*6.10*6.10*3.70
VERANDHA FF	1*31.00*1.80*3.70
CLASS ROOM FF	1*8.80*8.00*3.70
CLASS ROOM SF	4*6.10*6.10*3.70
CLASS ROOM SF	1*8.60*8.00*3.70

"THIS CERTIFICATE IS ISSUED ON THE BASIS THAT, THE ITEM 9 IN CHECK LIST MUST BE CERTIFIED BY AN APPROVED WIRE MAN AND THE SAME BE RECORDED SEPERATELY AND KEPT WITH SCHOOL HEAD WITHIN ONE MONTH OF THIS REPORT"




ASST ENGINEER
L.S.G.D
MUNICIPAL OFFICE
NORTH PARAVUR

Name of school

MAR GREGORIOS E.M SCHOOL, NORTH
PARAVOOR

DETAILS OF BUILDING

TWO STORIED BUILDING (NORTH SIDE)

RCC BUILDING BLOCK 1

CLASS ROOM GF	1*6.00*6.00*3.55
STAFF ROOM GF	2*6.00*6.00*3.55
STAFF ROOM GF	1*9.00*6.00*3.55
OFFICE ROOM GF	1*9.00*2.00*3.60
CLASS ROOM FF	3*6.00*6.00*3.55
COMPUTER ROOM FF	1*6.00*6.00*3.55
CLASS ROOM SF	4*6.00*6.00*3.60

RCC BUILDING BLOCK 2


CLASS ROOM GF	3*6.10*6.10*3.60
VERANDHA GF	1*22.40*1.80*3.60
CLASS ROOM FF	3*6.10*6.10*3.60
VERANDHA FF	1*22.40*1.80*3.60

RCC BUILDING BLOCK 3

STAGE	1*10.00*8.60*3.60
CLASS ROOM GF	4*6.10*6.10*3.70
VERANDHA GF	1*31.00*1.80*3.70
CLASS ROOM FF	4*6.10*6.10*3.70
VERANDHA FF	1*31.00*1.80*3.70
CLASS ROOM FF	1*8.80*8.00*3.70
CLASS ROOM SF	4*6.10*6.10*3.70
CLASS ROOM SF	1*8.60*8.00*3.70

"THIS CERTIFICATE IS ISSUED ON THE BASIS THAT,THE ITEM 9 IN CHECK LIST MUST BE CERTIFIED BY AN APPROVED WIRE MAN AND THE SAME BE RECORDED SEPERATELY AND KEPT WITH SCHOOL HEAD WITHIN ONE MONTH OF THIS REPORT"




ASST ENGINEER
L.S.G.D
MUNICIPAL OFFICE
NORTH PARAVUR